

Oil Field Environmental Incident Summary

Incident: 20160401124748 **Date/Time of Notice:** 04/01/2016 12:47

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: ODEGAARD STATE 31X-16BXC

Field Name: MIDWAY

Well File #: 29969

Date Incident: 3/31/2016 **Time Incident:** 11:15

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 95

Sec: 16

Qtr:

Location Description: Oil misted south off location affecting an area 100' x 50'

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 6506
321 22ND AVE E
WILLISTON, ND 58801

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	10	Gallons

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 3/29/2016

Risk Evaluation:

No personnel were in the vicinity of the flare.

Areal Extent:

100' x 50' South off location

Potential Environmental Impacts:

Minimal - very small spill volume travelled off location. No other environmental receptors were observed.

Action Taken or Planned:

The well was shut in immediately.

Wastes Disposal Location: To be determined...

Agencies Involved:

Updates

Date: 4/1/2016 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas outside the well lease. Follow-up is necessary.

Date: 5/17/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 13:09, 5/17/16.

No sign of impacts at the time of inspection.

No follow-up is necessary.